


# RemotePro Grounding Recommendations



Metal Pipe

Wind Turbine

Solar Panel

Enclosure

**Note:** For a wooden pole:

1. Run a 4 AWG copper wire from top to bottom of pole.
2. Connect the Wind Turbine Metal, the Solar Mount metal and the Enclosure metal to the 4 AWG copper wire using 4-6 AWG copper wire.

4-5 AWG Copper Wire

Ground Clamp

Ground Clamp

5/8" x 10' Copper Ground Rod